ANNEXURE—'B'

To Starred L.A. Question No. 284 By Shri B. G. Banakar, M.L.A.

Sl. No.	Name of the Taluk	Place	No. of Shed under Constn.
1	Kolar	Tamka	12
2	Tiptur	Tiptur	8
3	Srirangapatna	Srirangapatna	6
4	Nanjangud (Dutch)	Nanjangud	8
5	Sakaleshapur	Sakaleshapur	12
6	Arsikere	Arsikere	8
7	Moodabidri	Moodabidri	8
8	Ranebennur	Ranebennur	4
9	Kumta	Kumta	16
10	Khanapur	Khanapur	8
11	Baihongal	Bailhongal	8
12	Bagalkot	Bagalkot	28
13	Humnabad	Humnabad	8
14	Chintamani	Chintamani	19

ಹಿರೇಕೆರೂರ ತಾಲ್ಲೂಕಿನ ಲೋಕೋಪಯೋಗಿ ರಸ್ತೆಗಳು,

೨೨೫ ಶ್ರೀ ಬಿ. ಜಿ. ಬಣಕಾರ್ (ಹಿರೇಕೆರೂರು).—ಲೋಕೋಪಯೋಗಿ ಮತ್ತು ನೀರಾವರಿ ಸಚಿವರು ಈ ಕೆಳಕಂಡ ಪ್ರಶ್ನೆಗಳಿಗೆ ದಯವಿಟ್ಟು ಉತ್ತರಿಸುವರೆ ?

ಅ) ೧೯೮೧–೮೨ ಹಾಗೂ ೧೯೮೨–೮೩ರಲ್ಲಿ ಧಾರವಾಡ ಜಿಲ್ಲಾ ಹಿರೇಕೆರೂರ ತಾಲ್ಲೂಕಿನಲ್ಲಿ ಲೋಕೋಪಯೋಗಿ ಖಾತೆಯವರು ಮಾಡಿಸಿದ ಕೆಲಸಗಳ ಹೆಸರು ಹಾಗೂ ಅವುಗಳಿಗೆ ಖರ್ಚು ಮಾಡಿದ ಹಣ ಎಷ್ಟು?

ಆ) ೧೯೮೩–೮೪ರಲ್ಲಿ ಸದರಿ ಇಲಾಖೆಯವರು ಹಿರೇಕೆರೂರ ತಾಲ್ಲೂಕಿನಲ್ಲಿ ಈವರೆಗೆ ಮಾಡಿರುವ ಕೆಲಸಗಳ ಹೆಸರು ಹಾಗೂ ಅವುಗಳಿಗೆ ಖರ್ಚಾದ ಹಣದ ವೊತ್ತವೆಷ್ಟು?

ಶ್ರೀ ಹೆಚ್. ಡಿ. ದೇವೆಗೌಡ (ಲೋಕೋಪಯೋಗಿ ಮತ್ತು ನೀರಾವರಿ ಸಚಿವರು).—

ಅ) ವಿವರಗಳನ್ನು ಲಗತ್ತಿಸಲಾಗಿದೆ.

ಆ) ವಿವರಗಳನ್ನು ಲಗತ್ತಿಸಲಾಗಿದೆ.

UNSTARRED L.A.Q. No. 225

Works taken up for Execution by P.W.D. during 1981-82, 1982-83 and 1983-84 in Hirekerur Taluk, Dharwad District.

Unstarred L.A. Question No. 225 tabled by Sri B. G. Banakar, M.L.A.

ABSTRACT

Sl. No.	Head of Account	Amount spent during (in lakhs)			total to date
		1981-82	1982-83	1983-84	
1	2	3	4	5	6
	Chief Engineer (C & B), Zone.				
1	480 CO on P.H.	1.25	1.33	...	2.58
2	488 CO on S.S. & Welfare	1.38	2.19	0.05	3.62
3	280 Medical	0.10	0.06	...	0.16
4	310 A.H.	1.04	0.04	...	0.08
5	305 Agriculture	...	0.17	0.15	0.32
	Total Buildings Plan	2.77	3.79	0.20	6.76
	537 CO R&B Asphalting of Roads strengthening Sub-grade preparing surface.	0.14	0.15	...	0.29
	-do- II other formation	0.98	6.11	2.26	9.35
	-do- III Bridges	...	0.67	0.69	1.36
	Total of 537 CO R&B	1.12	6.93	2.95	11.00
	337 R&B Master Plan C.D. Works	1.04	0.01	0.09	1.15
	337 I.C.R.C.	1.91	0.04	0.13	2.08
	-do- Construction of Missing link	0.51	0.10	...	0.61
	-do- Constn of Bridge Minor	...	0.17	0.15	0.32
	-do- MNP Roads	...	..		...
	Total 337 R&B Plan	3.46	0.32	0.37	4.15

	337 R&B Special Repairs and Renewals to Roads.				
1	M.D.R.	0.93	2.00	0.18	3.11
2	O.D.R.	1.89	3.30	0.31	5.50
3	Village Roads	1.70	3.30	0.76	5.76
	Total	4.52	8.60	1,25	14.37
	Total of C&B Zone	11.87	19.64	4.77	36.24
	Chief Engineer (M.I.) Zone.				
1	506 CO On M.I. I–Constn. of New Tanks	0.79	1.27	0.26	2.32
2	III L.I.S.	8.86	9.85	1.75	20.46
3	V–Anicuts	0.93	0.89	0.60	2.42
	Total for 506 CO.M.I.	10,58	12.01	2.61	25.20
	305 M.I. Plan	1.94	1.19	0.01	3.14
	306 M.I. SR to Tanks	2.11	1.59	0.55	4.25
	Total for 306 M.I. Plan & Non–Plan	4.05	2.78	0.56	7.39
	Total for M.I. Zone.	14.63	14.79	3.17	32.59
	Grand Total for Chief Engineer C&B, and M.I. Zone.	26.50	34.43	7.94	68.87
2	Impts to Tuminkatti Hallur road	...	1.31	0.03	
3	do Byadgi Rattihalli road	...	2.05	0.75	
4	do Rattihalli roadvia Shirumbi	...	0.45	0.13	
5	do Tattihalli Tadkanhalli via Totgudi	...	0.67	0.33	
6	do to Hirekerur to Satenhalli	...	...	...	
7	do to Godehikonda Rottihalli via Arikatti Betkerur to Haunsabhavi Chikkerur road	...	...	...	
	Total	0.98	6.17	2.26	
	537 R & B I road MNP (KRBFF)				
1	Approach road to Kudpali village cross 4.50 KM	...	...	...	

1	2	3	4	5	6
	237 C.O. R & B Approach ;				
1	Approach road to Guggavankoppa Lamani tanda KM 4	...	...	...	
	537 C.O. on R & B III Bridge ;				
1	Approach road to yeliwal bridge to Ramtirth bridge via Chapradahalli	...	0.55	0.62	
2	Impts. to road from Rattihalli bridge to Kudpali	...	0.12	0.67	
3	Consnt. Causeway across Kumdwati river near Hiremadapur	...	...	...	
4	Yadgod near Madapur village	...	...	...	
	Total	...	0.67	0.69	
	506 C.O. on new tank ;				
1	Consts new tank at Galginkatti	0.11	0.02	...	
2	do Jokinhalli	0.68	1.06	0.04	
3	do Guddadamadapur	...	0.13	0.22	
4	do Gangikoppa	...	0.06	...	
	Total	0.79	1. 7	0.26	
	506 C.O. on V.R. Anicuts Pickups & Bhandara				
1	Constg barrage across Kumdawathi River near Hiremorab	0.93	0 89	0.60	
	Total	0.93	0.89	0.60	
	506 C.O. on MI. III. L.I.S.				
1	Constg. L.I.S. at Bhairampad	0.30	0.10	...	
2	do Rattihalli	1.80	4.82	0.11	

3	do	Madag Masur	6.76	4.92	1.68
4	do	at Ramtirth	...	...	...
		Total	8.86	9.85	1.79
	280 Medical ;				
1	Constg. P.H.C. at Kadur		0.10	...	...
2	do	Tawargi	...	0.06	...
		Fotal	0.10	0.06	...
	310 Animal Husbandary				
1	Constg of Ball shed and compound wall at Vetenary hospital Hirekerur		0.04	...	...
		Tctal	0.04	...	...
	337 R & B C.D. Master Plan				
1	Constructing low-level Causeway on Dadihalli Hiremattur road		0.21	...	...
2	do	H.P. drain 200 mm dia 2 rows on Hirebudihal to join H.S. Road	0.10	...	...
3	do	Dudihalli Rattihalli road	0.65	(—)0.09	..
4	Constn. of C.D. work approach to Yelawatti		0.08	010	0.09
		Total	1.04	0.01	0.09
	337 R & B I.C.R.C.				
1	Constg. road from Jawalli to Chikkerur		0.28	...	...
2	do	Khachavi to Chikkonati	0.58	0.11	...

1	2	3	4	5	6
3	do Aladagatti to Dupadahalli	0.63	...	...	
4	do Kyathanakeri to Rattihalli	0.21	0.45	...	
5	do road H.S. road Vadaranhall via B.R. road Ujjanipur Bohapur Hirebudihal	0.21	0.03	...	
6	Constg. road from Rattihalli to Anaji	...	0.25	0.13	
7	Constg. road to across to Paravathsiddgiri village	...	...	...	
	Total	1.91	0.84	0.13	
	337 R B Missing Link				
1	Constg. Causeway in KM 6.10 of Dudihalli Rattihalli Road	0.51	...	...	
2	do C.D. work on Bardikatti on Karnahalli Road	...	0.10	...	
	Total	0.51	0.10	...	
	306 M.I. Plan				
1	Impts. to Tank at Ablur	0.04	...	...	
2	do 296/308 Chinmulagund	0.25	...	...	
3	do 56 of Yegikoppa	0.30	...	...	
4	do 24 of Purpundikoppa	0.19	0.01	...	
5	do 16 of Haunsbhavi	0.36	...	...	
6	do 47 of Yemmiganur	0.25	0.18	...	
7	do 202 of Dudihalli	0.26	0.17	...	
8	do 49 of Betkerur	0.18	...	...	
9	do 77 of Agargatti	0.01	...	...	
10	do 43 of Yellapur	0.10	0.30	...	
11	Providing Yaragunta or Karur slab ling canal of tank in Sy. No. 49 of Batkerur	...	0.17	...	

12	Impts. to tank in Sy. No. 138 Hiremathur and 170 Chikkamattur	...	0.34	...
13	do 75 of Chikkabadihal	...	0.01	...
14	Providing lining with C.C. Yerguntla slab lining and Irrigation canal to tank in Sy. No. 16 of Haunsbhavi	...	0.01	...
15	Providing Yeraguntalal slab lining canal of tank in Sy. No. 43 of Yellapur	...	...	0.01
	Total	1.94	1.19	0.01

337 R & B Repairs to Bridges.

1	Repaire to bridge across Kumdwathi River on T.T. Road KM. 13	...	0.01	...
2	Winding arch bridge in KM 10 of Haunsbhavi Chikkerur Road KM. 12	...	0.12	0.15
3	Constg. H. P. culvert on Masur Madag Herenahalli Road	...	0.04	...
	Total	Nil	0.17	0.15

305 Agriculture (WBA)

1	Const. Quarters for Agricultural Officer at Ratihalli	...	0.37	0.07
2	-do- Assistant Qtrs. at Rattihalli	...	0.23	0.04
3	-do- Agricultural Assistant Quarters at Chinnamulgund	...	0.06	0.07
4	-do- Makari	...	0.04	0.03
	Total	...	0.70	0.21

1	2	3	7	5
	337 R & B M.N.P.			
1	Improvements to Road from Kod to Kalagonda KM 4.0 to 9/5	...	0.78	0.08
2	Constg. Road from T.T. Road to cross to join Bullapur	...	0.30	...
3	approach Road to Agragatti	...	0.38	...
	Total	...	1.66	0.08
	337 R & B O.D.R.S.R.			
1	Remetalling in Km. 6 of Tuminakatti Hallu Road.	0.15	...	...
2	-do- Km 2 -do-	0.14	...	...
3	-do- Km. 3 -do-	0.14	...	...
4	-do- Km 4 -do-	0.14	...	...
5	-do- of Haunsbhavi, Chikkerur road Km. 7&8	0.03	...	...
6	Remetalling Km. 5 of Tumminakatti Hallur road	0.07	...	...
7	Providing resurfacing Km. 9/0 to 10/0 of T.H. road	0.14	...	...
8	Metalling Km. 8. of T.H. road	0.08	...	...
9	-do- 7 -do-	0.08	...	...
10	-do- 9 -do-	0.09	...	...
11	Providing Resurfacing to the 11th Km of Tumminakatti Hallur road	0.10	...	...
12	Providing resurfacing of Tumminakatti Hallur road	...	0.14	0.01
13	Widening Masur Shikaripur road Km. 5	0.21	0.06	0.02
14	Recarpeting Masur Shikaripur road Km. 1	...	0.36	...
15	-do- Haunsbhavi Chikkerur road Km. 5	...	0.24	...
16	Constg. of Side drain on Haunsbhavi Chikkerur road in Chikkerur town limit	...	0.11	0.01
17	Recarpetting Haunsbhavi Chikkerur road Km. 6	...	0.25	...
18	-do- Masur Shikaripur road Km, 1	...	1.14	...
	Total	1.89	3.30	0.31

1	2	3	4	5	6
	337 R & B A Dist road VIIIth S. R. to M.D.R.				
1	S.R.i.e. Recarpeting Masur–Hallur road 15 to 16	0.10	...	...	
2	Providing 2 cm thick asphalt carpet for resurfacing Km 31. to 32 of H. S. road.	0.10	...	...	
3	Recarpeting Km. 11 of Hirekerur Kod road	0.11	...		
4	-do- Hirekerur–Chikkerur road	0.08	...	...	
5	S.R. i.e. pot hole filling Km. No. except 1, 2, 5, 8 of Masur Hallur road	0.13	...	...	
6	Filling of pot hole of Masur Hallur road Km 2 to 19 (except Km. 6 to 8)	0.09	...	...	
7	Recarpeting Masur Hallur road 5 & 8	0.22	...	...	
8	S.R. i e. Recarpeting Masur Hallur road Km. 5 & 8	...	0.06	...	
9	-do- -do- 4	...	0.17	...	
10	-do- -do- Km. 2 of Hirekerur Shiralakoppe	...	0.13	...	
11	Constg. of side drain on either side of Hirekerur Chikkerur road.	...	0.30	...	
12	Recarpeting in Km. 1 & 2 of Hirekerur Haunsbhavi road	0.09	0.36	...	
13	-do- Km. 2 & 3 of -do-	...	0.27	...	
14	-do- Hirekerur Shiralakeppa road Km. 3	...	0.27	...	
15	-do- Hirekerur Chikkerur road Km. 1	...	0.14	...	
16	-do- Hirekerur Kod road Km. 3	...	0.26	...	
17	S R. i e. Recarpetting Hirekerur Haunsbhavi road Km. 1. 2 & 3.	...	0.04	...	
18	Recarpeting in Km. 0/0 to 1/0 of Hirekerur Haunsbhavi road	...	...	0.16	
19	-do- Hirekerur Chikkerur road Km. 1 & 9	...	...	0.02	
	Total	0.93	2.00	0.18	

1	2	3	4	5
	337 R & B to village roads			
1	Recarpeting Byadgi Rattihalli road	0.04	...	...
2	-do- Km. No. 27	0.02	...	...
3	S.R. i.e. Metalling at Dudihalli Rattihalli road Km 5 & 6	0.06	...	...
4	Widening Masur Shikaripur road KM 5	0.01	...	...
5	Resurfacing Kudpali Kacivi road 0/0 to 1/0	0.11	...	...
6	-do- Surkoti approach road	0,21	...	...
7	Providing resurfacing Km 10 Tuminkatti Hallu road	0 02	...	...
8	Constg, low level causeway in Km. No. 0.40 to Rattihalli Anaji road.	0.24	0.07	...
9	Providing 2 cm thick premixed asphalt carpet to Km 12 & 13 of T. T. road	0.24	0.22	...
10	Resurfacing Chikkerur Mallenhalli road Km. 0/0 to 0/80.	0.09	0.03	...
11	Motebannur Surdikatti Karmahalli road	0.06	0.16	...
12	S.R. i.e. Metalling Dandigihalli Hiremattur road Km. 9	0.07	0.06	...
13	-do- Km. No. 2	0.12	0.03	...
14	-do- Km. No.	0.13	0.03	...
15	Recarpeting to Masur Hanmanhalli road 0/0 to 0/50	...	0.20	...
16	Resurfacing & asphalting to Km. 0.50 to 1.00 of Madag Masur	0.08	0.30	...
17	Resurfacing & Asphalting road from Gumnalbride. to Join H. S. Road Km. No. 2	0.04	0.38	...
18.	-do- Chikerur to Gumnal bridge Road 0 to 1.60	...	0.11	...
19.	Resurfacing of K M 20 th of T. T. Road.	...	0.18	...
20.	S. R. to Hosalli road on Km 1 & 3	0.16	0.11	...
21,	Resurfacing of Dandigihalli Hiremattur road K M No. 7	...	0.10	...

22.	-do- K M No. 3	...	0.11	...
23.	S. R. to Hirekerur varah road K M No. 1	...	0.15	...
24.	Resurfacing Chikkerur Gumnal road O. O. to 1/O	...	0.09	...
25.	Providing soling Yettihalli approach road K M O to 9.4.	...	0.05	...
26.	Resurfacing Masur Madag road Haranhalli	...	0.08	...
27.	-do- Hirekery Varah road.	...	0.14	...
28.	S R. to Kod-Chikerur road 1 K M 13.	...	0.06	...
29.	Resurfacing K. M 1 of Yadged Makari road	...	0.35	...
30.	Resurfacing asphalting & village limit of Hadrihalli Balembid road Godchikonda K H R Haunsabhavi ruad to Join Kod-Chikerur road.	...	0.20	0.10
306 M. I. IV th S. R.				
1.	Constg. of H. P. drain in tank in Sy. No.231/256 of Chikkerur.	0.03	...	...
2.	Impts. to tank in Sy. No. 33 of Vadenapur.	0.25	...	...
3.	S: R. to tank in Sy. No. 419 of Chinnamulgund	0.29	...	...
4.	-do- 58 of Jawalli.	0.25	0,05	...
5.	-do- 69 of Bhogavi.	0.05	...	...
5.	Impts, to tank in Sy. No. 24 of purpundikoppa.	0.07	...	...
7.	Reconstg. of C. D. Work in K M of 9 on Right Bank canal at Madag Masur tank.	0.06	...	...
31.	Resurfacing of Gundgatti to Hireyadehi Road K M No. 1	0.09	...	0.05
31	(ai -do- Kot. 2	...	...	0.42
32.	Providing soling to Godchikonda Mattihalli road via Arikatti Botkerur K M No. 3	...	...	...
33.	-do- K M No. 1	...	...	0.05
34.	Resurfacing Dandigihalli Hiremattur road K M No. 3	...	...	0.07
35.	Resurfacing -do- K M No- 7	...	...	0.06
36.	S. R, to Kod Chikerur road K M No. 12 & 14	...	...	0.12
	Total.—	1.70	3.30	0.76

1	2	3	4	5
8.	Urgent Repairs to tank in Sy. No. 213 of Kod	0.01	...	...
9.	Repairs to feeder channel of tank in Sy. No. 112,144 76 of Hosalli.	0 20	...	...
10.	-d- 16 of Haunsbhavi.	0.01	...	...
11	S. R. to tank in Sy. No. 147 of Purpundikoppa.	0.30	0.08	...
12.	S. R. to flood damage to tank in Sy. No. 53 of Gundagatti.	0.10	0.02	...
13.	Imptts. to Madag Masur tank canal constg. of field outlet on R. B. Canal from Km 6.40 to 10.30	0.09	...	...
14.	Constg. of H. P. drain across waste Weir canal of tank in Sy. No. 40 of Sriramanakoppa.	0.17	...	...
15.	S. R to tank in Sy. No. 17 of Yellapur.	0.13	...	...
16.	-do- 160 Gundagatti.	0.01	...	...
17.	-do- 77 of Angaragetti-	0.05	...	...
18.	Constg. of sluice revetment to the tank bond of tank in Sy. No. 170/13 of Chikkmattur.	0.02	0.12	...
19.	Constg. field outlet R. B. C. of Madag-Masur tank.	0.01	...	...
20.	Constg. of H. P. drain across waste weir channal of tank in Sy. No 40 Sriramanakoppa.	...	0.05	...
21.	S. R. to tank in Sy, No. 57 of Nidaregal.	...	0.11	...
22.	-do- 121 of Aralikatti.	...	0.13	...
23	Constg. sluice and providing revetment in Sy. No. 48 of Nulgeri.	...	0.06	...
24.	Constg. H. P. drain of tank in Sy. No, 251/256 of Chikkerur.	...	0.02	...
25.	S. R. i. e. providing lining from Km. 6.5 to 7.5 of Madag Masur tank.	...	0,43	...
26.	S. R. to tank in Sy. No. 314 of Haunsbhavi.	...	0.17	...

27.	ydo- 75 of Chikkabudihal.	...	0.12	...
28.	-do- 117 of Madlur.	...	0.07	0.08
29.	-do- 25 of Satenahalli.	...	0.06	0.02
30.	-do- 224/95 Burdikatti.	...	0.09	0.08
31.	-do- 194 of Haunsbhavi.	...	0.01	0.17
32.	Repair W. Wr. sluice bund of tank in Sy. No. 28 Kyathankeri.	...	...	0.10
33.	Widening of extsting two rows of 900 mm H. P. culvert across Chikkerur Shiralakoppa road in Shikaripur Talukiimit to in channel of Sqm. 192 of Chikaripur.	...	...	0.10
	Totai	2.11	1.59	0.55